# Field Report for Airborne Data Collected In Support of US EPA Region VI Tri-Chem Industries Fire 15 March 2018

#### **Background**

On 15 March 2018 a reported explosion and fire developed at the Tri-Chem Industries facility located 4.5 kilometers North West of Cresson, TX. Local news organizations reported heavy black smoke with periodic explosions. A number of fire companies were deployed from Fort Worth. The facility reported through Tier II reports to have a number of organic and inorganic compounds including acetic acid, aqua ammonia, dipropylene glycol methyl ether, and phosphoric acid. The US EPA Region VI requested that the ASPECT system be deployed to support ongoing activities at the site at approximately 1200 (local) on 15 March 2018. ASPECT was formally notified to launch at 1210 and was airborne at 1305. Since the fire was within the metro-plex area, flight time to the target was estimated at 25 (arrival at 1330) minutes.

The Tri-Chem facility is located 4.5 kilometers north of Cresson, TX on Cresson Highway. The geographical coordinates of the facility are 32.5520N, 97.6591W (figure 1). The area is a very flat with the town of Cresson being the only nearby residential area.



Figure 1: Tri-Chem Industries, Cresson, TX

## ASPECT response to this Mission/Incident was in support of:

US EPA Region 6. OSC: Adam Adams

#### **ASPECT System**

The US EPA ASPECT system collects airborne infrared (IR) images and chemical screening data from a safe distance over the site (about 3,000 ft AGL). The system consists of an airborne high speed Fourier transform infrared spectrometer (FTIR) coupled with a wide-area IR line scanner (IRLS). The ASPECT IR systems have the ability to detect compounds in both the 8 to 12 micron (800 to 1200 cm-1) and 3 to 5 micron (2000 to 3200 cm-1) regions. The 8 to 12 micron region is typically known as the atmospheric window region since the band is reasonably void of water and carbon dioxide influence. Spectrally, this region is used to detect carbon - non-carbon bonded compounds. The 3 to 5 micron region is also free of water and carbon dioxide but typically does not have sufficient energy for use. This band does show use in high-energy environments such as fires. The carbon - hydrogen stretch is very common in this region.

A digital Nikon DX2 camera (12.4 mega pixel CMOS 3:5 aspect ratio, 28 mm wide-angle lens) collects visible aerial imagery as part of the core data product package. The camera timing system is connected to the primary IR sensors and provides concurrent image collection when other sensors are triggered. All imagery is geo-rectified using both aircraft attitude correction (pitch, yaw, and roll) and GPS positional information. Imagery can be processed while in flight or approximately 600 frames per hour can be processed once the data are downloaded from the aircraft.

An Imperx mapping camera (29 mega pixels; mapping focal plane array) provides a similar aspect ratio and aerial coverage. Like the Nikon DX2, it is connected to the primary IR sensors and provides concurrent image collection when other sensors are triggered. These images are often digitally processed in lower resolution so they can be transmitted via satellite communication. The high resolution images (>20 MB each) are pulled from the ASPECT after the sortie and are available at a later time.

All aerial photographic images collected by the ASPECT system are ortho-rectified and geospatially validated by the reachback team. In general, this consists of conducting georegistration using a Digital Elevation Model (DEM) which promotes superior pixel computation and lessens topographic distortion. The image is then check by a team member (using a Google Earth base map) for proper location and rotation

Data is processed using automated algorithms onboard the aircraft with preliminary results being sent using a satellite system to the ASPECT reachback team for QA/QC analysis. Upon landing preliminary data results are examined and validated by the reachback team.

ASPECT data provides complete GIS compatibility with a number of systems including Google Earth and ESRI ArcView. For this response, data is being provided in a Google Earth format

with uses a KML format file. The KML n-link file is a collection of Google Earth KML scripts that permits full viewing and download of data associated with a given deployment or project. Once the n-link has been loaded on your computer, subsequent installs of the link are unnecessary for the duration of the project or deployment; as new data is added to the project, the n-link, when opened will show the new data in chronological order. Two software packages are necessary to run the n-link. You will need an installed copy of Google Earth and a current copy of your favorite internet browser (Internet Explorer, Chrome, or Firefox) your internet browser.

# **Weather Conditions and Crew Report**

Weather conditions for the Cresson area at the time of data collection consisted of clear skies with about 16 km (10 miles) of visibility. Winds were from the south at 5 m/sec (20 mph). The surface temperature was 22°C with a humidity of 42%. Pressure was reported as 1012 mb. Winds at altitude were reported to be about 22 kts from the south. The crew reported very little smoke with a faint smoke plume moving to the north suggesting that the fire about to burn out.

## **Flight Status**

The order to launch the aircraft was given 1305 local on 15 March 2018 and the aircraft was on station at 1330. The aircraft made a total of 15 data collection passes; flight information is summarized in Appendix A and Figure 2.



Figure 2: Data collection passes, Tri-Chem Industries, Cresson, TX

#### **Data Results**

#### **Line Scanner Data Results**

A total of 1 test and 15 data passes were made in the proximity of the site and an infrared line scanner image were generated for each pass. Figure 3 shows a typical 3-band image obtained from data collected in run 15. Objects that are hot will appear white while cold images will appear black. The white shades of the structure indicate that this area of the image is hot; consistent with a fire. No plume was observed in any of the data collection passes.



Figure 3: – 3 band IR image, Run 15, Tri-Chem Industries

#### **FTIR Data Results**

FTIR Spectral data was collected for each pass at a resolution of 16 wavenumbers. ASPECT uses an automated detection algorithm to permit compounds to be analyzed while the aircraft is in flight. 78 compounds are included in this algorithm and the list and associated detection limits are given in Table 1. In addition, collected data are also manually analyzed by comparing any detected spectral signatures to a collection of published library spectra.

Organic compounds including 1-butene, 2-butene and isobutylene were observed in three data passes with the locations given in Figure 4. These compounds are common products of combustion. On data pass 3 an isolated and low level detection of 1-butene was made north of the facility (downwind) and across the highway. On pass 15 and 16 the system was flown approximately 50 meters downwind of the facility building. These passes showed several compounds including 1-butene, 2-butene, isobutylene and a very low concentration of ally alcohol; all below 2 ppm. Additional compounds were also detected and included ozone and peroxyacyl nitrates (PAN) being generated by the hot fire. Post analysis of data showed a low presence of acetone with a maximum concentration of 0.7 ppm. A summary of the chemical detections is given in Table 2. A typical example of confirmation spectra is given in Figure 5. This image shows isobutylene characteristic of the major peak located at 890 wavenumbers.

**TABLE 1 – Chemicals Included in the ASPECT Auto-Processing Library** 

Acetic Acid	Cumene	Isoprene	Propylene
Acetone	Diborane	Isopropanol	Propylene Oxide
Acrolein	1,1-Dichloroethene	Isopropyl Acetate	Silicon Tetrafluoride
Acrylonitrile	Dichloromethane	MAPP	Sulfur Dioxide
Acrylic Acid	Dichlorodifluoromethane	Methyl Acetate	Sulfur Hexafluoride
Allyl Alcohol	Difluoroethane	Methyl Ethyl Ketone	Sulfur Mustard
Ammonia	Difluoromethane	Methanol	Nitrogen Mustard
Arsine	Ethanol	Methylbromide	Phosgene
Bis-Chloroethyl Ether	Ethyl Acetate	Methylene Chloride	Phosphine
Boron Tribromide	Ethyl Formate	Methyl Methacrylate	Tetrachloroethylene
Boron Triflouride	Ethylene	MTEB	1,1,1-Trichloroethane
1,3-Butadiene	Formic Acid	Naphthalene	Trichloroethylene
1-Butene	Freon 134a	n-Butyl Acetate	Trichloromethane
2-Butene	GA (Tabun)	n-Butyl Alcohol	Triethylamine
Carbon Tetrachloride	GB (Sarin)	Nitric Acid	Triethylphosphate
Carbonyl Chloride	Germane	Nitrogen Trifluoride	Trimethylamine
Carbon Tetraflouride	Hexafluoroacetone	Phosphorus Oxychloride	Trimethyl Phosphite
Chlorodifluoromethane	Isobutylene	Propyl Acetate	Vinyl Acetate

A comparison of the detected compounds and those listed on the Tier II report for the facility tends to show consistency. The allyl alcohol detected is characteristic of a heavy alcohol with a number of peaks from 900 to 1200 wavenumber. The report shows that 2(2-butoxyethoxy) ethanol is stored on-site and has an IR signature similar to that of allyl alcohol, namely a wide signature centered around 1100 wavenumber. Also, diacetone alcohol has IR spectra showing the characteristic peaks of acetone between 1050 and 1300 wavenumbers.



Figure 4: Chemical Detection Locations, Tri-Chem Industries




Figure 5: Isobutylene Spectra, Tri-Chem Industries

**Table 2. Chemical Results Summary** 

Table 2. Chemical Results Summary						
Run	Date	Time	Chemical	Max		
		(UTC)		Concentration		
				(ppm)		
1	15 March	1818	Test	Test		
2	2018	1832	None	None		
3		1835	1-butene	1.296		
4		1838	None	None		
5		1842	None	None		
6		1848	None	None		
7		1855	None	None		
8		1902	None	None		
9		1906	None	None		
10		1909	None	None		
11		1913	None	None		
12		1917	None	None		
13		1925	None	None		
14		1931	None	None		
15		1934	2-butene	2.805		
			isobutylene	1.898		
			Allyl	0.718		
			alcohol			
16		1938	1-butene	1.655		
			2-butene	1.967		
			Acetone	0.390		

#### **Aerial Photography Results**

A full set of high resolution aerial digital photography was collected as part of the flight. Figure 6 shows a representative image collected as part of Run 5. This image has been orthorectified with the top of the image being north. The facility which is located in the center of the frame clearly shows damage to the roof. Close examination shows the presence of a very light plume moving to the north. Figure 7 shows a typical oblique image collected from the right side of the aircraft. This image is not geo-rectified. The top of the image is looking to the east. Examination of the image clearly shows the extent of collapse of the roof with a small amount of smoke being emitted on the southern part of the building.

#### **Conclusions**

ASPECT was dispatched at the request of the EPA Region VI emergency response program to provide air monitoring of the Tri-Chem Industries fire. ASPECT arrived on-site at 1330 (local) and noted a light colored plume moving toward the north. Initial data passes north of the facility (downwind) showed an isolated detection of 1-butene northwest of the facility. On pass 15 and 16 the system was flown so a close ground track passes immediately north of the facility. These passes showed several compounds including 1-butene, 2-butene, and isobutylene;

all below 2 ppm. Very low levels of acetone (less than 1 ppm) were also detected immediately downwind of the facility. IR imagery collected over the site clearly showed the elevated temperature of the structure but did not show any emission being generated by the facility.



Figure 6: Aerial image Tri-Chem Industries



Figure 7: Oblique Image Tri-Chem Industries.

# Appendix A.

#### Mission Log

Mission: 2018-03-15 Tri Chemicals

Date: 3/15/2018 Time UTC: 18:18

Aircraft Number: N9738B

DEM: Using elevation from DEM Database

\_\_\_\_\_

Run: 1 Time: 18:22:02 UTC

Alt: 3572 ft MSL Elev: 785 ft Elevation from DEM Database

Vel: 145 knots Heading: 244

# Digitals: 5

24mm2018\_03\_15\_18\_21\_34.jpg

24mm2018\_03\_15\_18\_21\_40.jpg

24mm2018\_03\_15\_18\_21\_47.jpg

24mm2018\_03\_15\_18\_21\_53.jpg

24mm2018\_03\_15\_18\_21\_59.jpg

# MSIC: 5

20180315182214277.jpg

20180315182220627.jpg

20180315182226991.jpg

20180315182233341.jpg

20180315182239706.jpg

#### FTIR: 1

20180315\_182206\_A.igm

IRLS: 1

2018\_03\_15\_18\_22\_07\_R\_01 TA=14.9;TB=34.7;Gain=3

Gamma Runs: None

-----

```
Alt: 3904 ft MSL Elev: 1109 ft Elevation from DEM Database
    Vel: 102 knots Heading: 265
Digitals: 3
    24mm2018_03_15_18_31_47.jpg
    24mm2018_03_15_18_31_53.jpg
    24mm2018_03_15_18_31_59.jpg
MSIC: 3
    20180315183227109.jpg
    20180315183233474.jpg
    20180315183238918.jpg
FTIR: 1
    20180315_183218_A.igm
IRLS: None
Gamma Runs: None
Run: 3 Time: 18:35:08 UTC
    Alt: 3927 ft MSL Elev: 1105 ft Elevation from DEM Database
    Vel: 106 knots Heading: 257
Digitals: 5
    24mm2018_03_15_18_34_41.jpg
    24mm2018_03_15_18_34_47.jpg
    24mm2018_03_15_18_34_53.jpg
    24mm2018_03_15_18_35_00.jpg
    24mm2018_03_15_18_35_06.jpg
MSIC: 5
    20180315183520532.jpg
    20180315183526881.jpg
    20180315183533230.jpg
    20180315183539595.jpg
    20180315183545944.jpg
FTIR: 1
    20180315_183512_A.igm
IRLS: 1
    2018_03_15_18_35_14_R_03 TA=15.0;TB=35.0;Gain=3
Gamma Runs: None
```

Run: 2 Time: 18:32:14 UTC

```
Alt: 4027 ft MSL Elev: 1087 ft Elevation from DEM Database
    Vel: 117 knots Heading: 260
Digitals: 3
    24mm2018_03_15_18_38_15.jpg
    24mm2018_03_15_18_38_22.jpg
    24mm2018_03_15_18_38_28.jpg
MSIC: 3
    20180315183855697.jpg
    20180315183902062.jpg
    20180315183908412.jpg
FTIR: 1
    20180315_183846_A.igm
IRLS: None
Gamma Runs: None
Run: 5 Time: 18:42:20 UTC
    Alt: 4019 ft MSL Elev: 1098 ft Elevation from DEM Database
    Vel: 99 knots Heading: 191
Digitals: 6
    24mm2018_03_15_18_41_52.jpg
    24mm2018_03_15_18_41_58.jpg
    24mm2018_03_15_18_42_04.jpg
    24mm2018_03_15_18_42_11.jpg
    24mm2018_03_15_18_42_17.jpg
    24mm2018_03_15_18_42_23.jpg
MSIC: 6
    20180315184231784.jpg
    20180315184238133.jpg
    20180315184244498.jpg
    20180315184250847.jpg
    20180315184257196.jpg
    20180315184303561.jpg
FTIR: 1
    20180315_184224_A.igm
IRLS: 1
    2018_03_15_18_42_25_R_05 TA=15.0;TB=35.0;Gain=3
Gamma Runs: None
```

Run: 4 Time: 18:38:43 UTC

Run: 6 Time: 18:48:26 UTC

Alt: 4021 ft MSL Elev: 1104 ft Elevation from DEM Database

Vel: 115 knots Heading: 266

Digitals: 3

24mm2018\_03\_15\_18\_47\_58.jpg 24mm2018\_03\_15\_18\_48\_04.jpg 24mm2018\_03\_15\_18\_48\_10.jpg

MSIC: 3

20180315184837671.jpg 20180315184844020.jpg 20180315184850385.jpg

FTIR: 1

20180315\_184829\_A.igm

IRLS: None

Gamma Runs: None

-----

Run: 7 Time: 18:55:56 UTC

Alt: 4089 ft MSL Elev: 1112 ft Elevation from DEM Database

Vel: 133 knots Heading: 264

Digitals: 3

24mm2018\_03\_15\_18\_55\_28.jpg 24mm2018\_03\_15\_18\_55\_35.jpg 24mm2018\_03\_15\_18\_55\_41.jpg

MSIC: 3

20180315185608905.jpg 20180315185615254.jpg 20180315185621619.jpg

FTIR: 1

20180315\_185600\_A.igm

IRLS: None

Gamma Runs: None

\_\_\_\_\_

```
Run: 8 Time: 19:02:37 UTC
    Alt: 3924 ft MSL Elev: 1104 ft Elevation from DEM Database
    Vel: 122 knots Heading: 263
Digitals: 4
    24mm2018_03_15_19_02_09.jpg
    24mm2018_03_15_19_02_15.jpg
    24mm2018_03_15_19_02_21.jpg
    24mm2018_03_15_19_02_28.jpg
MSIC: 4
    20180315190249286.jpg
    20180315190255635.jpg
    20180315190301095.jpg
    20180315190307444.jpg
FTIR: 1
    20180315_190240_A.igm
IRLS: 1
    2018_03_15_19_02_42_R_08 TA=15.0;TB=35.0;Gain=3
Gamma Runs: None
______
Run: 9 Time: 19:06:02 UTC
    Alt: 3702 ft MSL Elev: 1103 ft Elevation from DEM Database
    Vel: 99 knots Heading: 260
Digitals: 3
    24mm2018_03_15_19_05_35.jpg
    24mm2018_03_15_19_05_41.jpg
    24mm2018_03_15_19_05_47.jpg
MSIC: 3
    20180315190615387.jpg
    20180315190620832.jpg
    20180315190627181.jpg
FTIR: 1
    20180315_190606_A.igm
IRLS: None
Gamma Runs: None
```

```
Run: 10 Time: 19:09:36 UTC
    Alt: 3868 ft MSL Elev: 1094 ft Elevation from DEM Database
    Vel: 110 knots Heading: 261
Digitals: 4
    24mm2018_03_15_19_09_08.jpg
    24mm2018_03_15_19_09_14.jpg
    24mm2018_03_15_19_09_20.jpg
    24mm2018_03_15_19_09_27.jpg
MSIC: 4
    20180315190947827.jpg
    20180315190954192.jpg
    20180315191000541.jpg
    20180315191006890.jpg
FTIR: 1
    20180315_190940_A.igm
IRLS: 1
    2018_03_15_19_09_41_R_10 TA=15.0;TB=35.0;Gain=3
Gamma Runs: None
Run: 11 Time: 19:13:37 UTC
    Alt: 3882 ft MSL Elev: 1093 ft Elevation from DEM Database
    Vel: 122 knots Heading: 262
Digitals: 3
    24mm2018_03_15_19_13_09.jpg
    24mm2018_03_15_19_13_15.jpg
    24mm2018_03_15_19_13_21.jpg
MSIC: 3
    20180315191349327.jpg
    20180315191355692.jpg
    20180315191401136.jpg
FTIR: 1
    20180315_191340_A.igm
IRLS: 1
    2018_03_15_19_13_42_R_11 TA=15.0;TB=35.0;Gain=3
Gamma Runs: None
```

Run: 12 Time: 19:17:29 UTC

Alt: 3828 ft MSL Elev: 1080 ft Elevation from DEM Database

Vel: 112 knots Heading: 264

Digitals: 3

24mm2018\_03\_15\_19\_17\_01.jpg 24mm2018\_03\_15\_19\_17\_08.jpg 24mm2018\_03\_15\_19\_17\_14.jpg

MSIC: 3

20180315191741763.jpg 20180315191748113.jpg 20180315191754462.jpg

FTIR: 1

20180315\_191733\_A.igm

IRLS: None

Gamma Runs: None

-----

Run: 13 Time: 19:25:34 UTC

Alt: 3874 ft MSL Elev: 1071 ft Elevation from DEM Database

Vel: 106 knots Heading: 263

Digitals: 2

24mm2018\_03\_15\_19\_25\_06.jpg 24mm2018\_03\_15\_19\_25\_19.jpg

MSIC: 3

20180315192546581.jpg 20180315192552930.jpg 20180315192559296.jpg

FTIR: 1

20180315\_192538\_A.igm

IRLS: None

Gamma Runs: None

\_\_\_\_\_

Run: 14 Time: 19:31:02 UTC Alt: 3911 ft MSL Elev: 1107 ft Elevation from DEM Database Vel: 110 knots Heading: 264 Digitals: 3 24mm2018\_03\_15\_19\_30\_34.jpg 24mm2018\_03\_15\_19\_30\_40.jpg 24mm2018\_03\_15\_19\_30\_47.jpg MSIC: 3 20180315193114339.jpg 20180315193120688.jpg 20180315193127053.jpg FTIR: 1 20180315\_193106\_A.igm IRLS: None Gamma Runs: None Run: 15 Time: 19:34:49 UTC Alt: 3925 ft MSL Elev: 1110 ft Elevation from DEM Database Vel: 116 knots Heading: 267

Digitals: 3

24mm2018\_03\_15\_19\_34\_21.jpg 24mm2018\_03\_15\_19\_34\_27.jpg 24mm2018\_03\_15\_19\_34\_33.jpg

MSIC: 3

20180315193501317.jpg 20180315193507666.jpg 20180315193514015.jpg

FTIR: 1

20180315\_193453\_A.igm

IRLS: None

Gamma Runs: None

\_\_\_\_\_

Run: 16 Time: 19:38:31 UTC

Alt: 4062 ft MSL Elev: 1111 ft Elevation from DEM Database

Vel: 105 knots Heading: 257

# Digitals: 4

24mm2018\_03\_15\_19\_38\_03.jpg

24mm2018\_03\_15\_19\_38\_09.jpg

24mm2018\_03\_15\_19\_38\_16.jpg

24mm2018\_03\_15\_19\_38\_22.jpg

# MSIC: 4

20180315193843742.jpg

20180315193850107.jpg

20180315193856456.jpg

20180315193902821.jpg

#### FTIR: 1

20180315\_193834\_A.igm

# IRLS: 1

2018\_03\_15\_19\_38\_36\_R\_16 TA=15.0;TB=35.0;Gain=3

Gamma Runs: None

# Appendix B

#### **Tabular Chemical Results**

```
20180315_183512_A_igm
1-butene
Estimated Detection Limit = 1.20 \text{ ppm}
Scan Latitude Longitude Concentration
                           ppm
1227 32.555622 -97.662639
                          1.205
<u>1228 32.555620 -97.662698 1.296</u>
20180315_193453_A_igm
2-butene
Estimated Detection Limit = 1.87 ppm
Scan Latitude Longitude Concentration
                           ppm
544 32.551679 -97.658588
                           2.089
545 32.551677 -97.658588
                           2.664
546 32.551673 -97.658587
                           2.447
547 32.551670 -97.658586 2.757
548 32.551668 -97.658585 2.450
549 32.551665 -97.658584 2.206
550 32.551662 -97.658583 2.437
551 32.551660 -97.658581 2.473
552 32.551658 -97.658580 2.609
553 32.551655 -97.658578 2.650
554 32.551653 -97.658576 2.279
555 32.551651 -97.658575 2.380
556 32.551657 -97.658619 2.351
557 32.551671 -97.658698 2.689
558 32.551668 -97.658697 2.805
559 32.551666 -97.658695 2.755
560 32.551664 -97.658693 2.352
561 32.551663 -97.658691 2.156
562 32.551661 -97.658690 2.181
563 32.551658 -97.658688 2.099
```

# 20180315\_193453\_A\_igm allyl alcohol Estimated Detection Limit = 0.53 ppmScan Latitude Longitude Concentration ppm 547 32.551670 -97.658586 0.635 548 32.551668 -97.658585 0.654 549 32.551665 -97.658584 0.607 550 32.551662 -97.658583 0.620 551 32.551660 -97.658581 0.718 552 32.551658 -97.658580 0.676 553 32.551655 -97.658578 0.624 554 32.551653 -97.658576 0.573 555 32.551651 -97.658575 0.545 556 32.551657 -97.658619 0.543 558 32.551668 -97.658697 0.563 559 32.551666 -97.658695 0.600 <u>560 32.551664 -97.658693 0.589</u>

#### 20180315\_193453\_A\_igm isobutylene Estimated Detection Limit = 1.50 ppmScan Latitude Longitude Concentration ppm 559 32.551666 -97.658695 1.650 560 32.551664 -97.658693 1.634 561 32.551663 -97.658691 1.640 562 32.551661 -97.658690 1.785 563 32.551658 -97.658688 1.886 564 32.551656 -97.658686 1.839 565 32.551653 -97.658685 1.898 566 32.551649 -97.658684 1.799 567 32.551646 -97.658683 1.896 568 32.551643 -97.658681 1.805 569 32.551640 -97.658680 1.755 570 32.551637 -97.658679 1.618 571 32.551636 -97.658690 1.515

```
20180315_193834_A_igm
1-butene
Estimated Detection Limit = 1.20 \text{ ppm}
Scan Latitude Longitude Concentration
                           ppm
875 32.551226 -97.658921
                           1.212
876 32.551216 -97.658918
                           1.255
877 32.551204 -97.658914
                           1.288
878 32.551195 -97.658911
                           1.335
879 32.551186 -97.658909
                           1.376
880 32.551177 -97.658906
                           1.392
881 32.551168 -97.658903
                           1.412
882 32.551160 -97.658900
                           1.433
883 32.551153 -97.658897
                           1.440
884 32.551146 -97.658895
                           1.417
885 32.551139 -97.658907
                           1.451
886 32.551134 -97.658979
                           1.481
887 32.551129 -97.659003
                           1.497
889 32.551120 -97.658999
                           1.514
890 32.551117 -97.658997
                           1.564
891 32.551113 -97.658995
                           1.618
892 32.551111 -97.658993
                           1.614
893 32.551108 -97.658991
                           1.696
894 32.551106 -97.658989
                           1.645
895 32.551105 -97.658988
                           1.644
896 32.551104 -97.658986
                           1.655
897 32.551103 -97.658985
                           1.654
898 32.551103 -97.658984
                           1.604
899 32.551103 -97.658983
                           1.528
900 32.551102 -97.658982
                           1.410
901 32.551102 -97.659037
                           1.365
20180315_193834_A_igm
2-butene
Estimated Detection Limit = 1.87 ppm
Scan Latitude Longitude Concentration
                            ppm
879 32.551186 -97.658909
                           1.996
892 32.551111 -97.658993
                           1.902
893 32.551108 -97.658991
                           1.930
```

894 32.551106 -97.658989

1.967

# $20180315\_193834\_A\_igm\\ acetone$

Estimated Detection Limit = 0.20 ppm Scan Latitude Longitude Concentration

Scan Latitude	Longitude	Concentration
		ppm
879 32.551186	5 -97.658909	9 0.226
883 32.551153	3 -97.65889	7 0.207
884 32.551146	5 -97.65889:	5 0.217
885 32.551139	9 -97.65890′	7 0.247
886 32.551134	4 -97.658979	9 0.203
889 32.551120	0 -97.658999	9 0.215
890 32.551117	7 -97.65899	7 0.225
891 32.551113	3 -97.65899	5 0.248
892 32.55111	1 -97.658993	3 0.271
893 32.551108	8 -97.65899	1 0.322
894 32.551100	5 -97.658989	9 0.335
895 32.551105	5 -97.658988	8 0.371
896 32.551104	4 -97.658986	6 0.390
897 32.551103	3 -97.65898	5 0.361
898 32.551103	3 -97.658984	4 0.283
899 32.551103	3 -97.658983	3 0.253